








HONDA

NO.	CAR INFO.	PART NO.	SPARK PLUG GASKET
1	F20A, F22A, F20B, F22B, F22B1	JSP100001 12342-PT0-000 x 4	
2	C32A1	JSP100001 12342-PT0-000 x 6	
3	B20A5, D13B, D15B, D15B6, D15B7, D16Y5, ZC, D16A7	JSP100002 12342-PJ7-000 12342-PM3-000 x 4	
4	B16A, B18A, B20A, H22A, H23A, ZC, B20B2	JSP100003 12342-PG6-000 x 4	
5	H22A7, H23A, ZC, D16A1	JSP100004 12342-PT2-000 x 4	
6	B18A, B20A, D15Z6, D16Y5, D15B2, D15Z1, D16Y7, D17A2, D15BB, K20A1/2, K24A4	JSP100005 12342-P08-004 12342-P2A-005 12342-P8A-A01 12342-PCX-004 x 4	
7	C30A	JSP100006 12342-PR7-A00 x 4	

HONDA

NO.	CAR INFO.	PART NO.	SPARK PLUG GASKET
8	CR-V 5-DOOR 2015~2017 ACCORD SEDAN 2013~2017 ACCORD COUPE 2013~2017	JSP100008 12342-5A2-A01	
9	CR-V 5-DOOR 2015~2017 ACCORD SEDAN 2013~2017 ACCORD COUPE 2013~2017	JR-Z01-100003 12343-5A2-A01 x 4 WASHERS*8	
10	2020~2001 ODYSSEY 3.5L V6 - Gas 2020~2001 PILOT, PASSPORT 3.5L V6 - Gas	JR-Z01-100004 12343-5G0-A01 x 4 WASHERS*8	
11	2018~2020 Accord 2.0L L4 - Gas 2018~2020 Civic 1.5L L4 - Gas, 2.0L L4 - Gas	JSP100011 12343-RPY-G01	
12	R18A1	JOT100031 30522-RNA-A01	